

/ Expro Excellence Well Intervention

Deepwater riser/BOP inspection with downhole video saves GOM operator \$1.5million as well as avoiding costly interventions in the future



Objectives

 An operator in the Gulf of Mexico (GOM) finished completing a deepwater well in 4,300 ft of water but wanted to inspect the 19" riser and BOP stack for debris that might be sitting on a ledge in the stack

Expro Excellence

• Expro recommended the ViewMax system, which combines the high-fidelity, fibre optic video system with the rotating side view camera providing a detailed view of the different elements within the BOP stack – a side view camera is the only absolute way of verifying if debris was in the stack on top of the rams without pulling out the riser and BOP to the surface

Value to client

- The downhole video images were instrumental in confirming the customer had nothing to worry about and they could continue to complete their well without fear of debris falling into the well
- Avoidance of potentially undertaking a multi-million dollar intervention in the future
- Estimated savings of approx. \$1.5 million

 based on the cost per day of
 deepwater drill ships and the time it
 would take to pull the riser and BOP
 stack to visually check for debris







If debris was present it could add significant costly delays or even jeopardise the completion if it fell in and lodged in the tubing hanger or down the well. This could happen during a BOP test, or a disconnect from the wellhead. It is far less costly for clients to be absolutely confident of no debris before releasing the rig. The only alternative to find out if debris was present would be to pull the riser and BOP stack to the surface, resulting in multi-million dollar costs to the project.

Expro Excellence

Contact

For further information, please contact:

Kevin Illingworth Well Intervention

kevin.illingworth@exprogroup.com www.exprogroup.com/wellintervention

Well Intervention